



5001 1,2 г.



5002 0,9 г.



5003 3,8 г.



5004 1,4 г.



5005 4 г.



5006 1,6 г.



5007 1 г.



5008 1,7 г.



5009 11,1 г.



5010 9,1 г.



5011 1,4 г.



5012 3,8 г.



5013 2,7 г.



5014 2,1 г.



5015 5 г.



5016 1 г.



5017 1,3 г.



5018 0,8 г.



5019 1,1 г.



5020 2,9 г.



5021 4 г.



5022 3,7 г.



5023 1,8 г.



5024 3,8 г.



5025 4,5 г.



5026 7,6 г.



5027 3,7 г.



5028 2,3 г.



5029 1 г.



5030 2,1 г.



5031 2,1 г.



5032 3,8 г.



5033 2,5 г.



5034 5,7 г.



5035 3,5 г.



5036 2 г.



5037 1,6 г.



5038 2,5 г.



5039 1,7 г.



5040 1,1 г.



5041 3,12 г.



5042 4,5 г.



5043 1,2 г.



5044 2,5 г.



5045 1,6 г.



5046 7 г.



5047 4 г.



5048 3,1 г.



5049 1,6 г.



5050 1,57 г.



5051 6,71 г.



5052 8,58 г.



5053 1,83 г.



5054 7,18 г.



5055 4,03 г.



5056 4,95 г.



5057 2,42 г.



5058 2,93 г.



5059 2,43 г.



5060 2,16 г.



5061 4,36 г.



5062 2,27 г.



5063 2,60 г.



5064 6,67 г.



5065 2,93 г.



5066 2,27 г.



5067 3,15 г.



5068 3,59 г.



5069_3,43 г.



5070 4,58 г.



5071 1,83 г.



5072 2,71 г.



5073 3,96 г.



5074 1,83 г.



5075 2,16 г.



5076 2,27 г.



5077 1,17 г.



5078 1,75г.
кр 1,25-62



5079 1,17 г.



5080 1,57 г.
кр 1,25-12



5001 (1.16)
Кр.2,0-6.



5002 (0.94)
Кр.2,0-6.



5003 (3.8)
Кр.3,0-12.



5004 (1.4)
Кр.2,0-12.



5005 (3.98)
Кр.3,0-12.



5006 (1.61)
Кр.2,0-12.



5007 (0.69)
Кр.2,0-6.



5008 (1.68)
Кр.2,0-5.



5009 (11.11)
Кр.1,25-78.



5010 (9.1)
Кр.3,0-32; кр.1,5-3.



5011 (1.4)
Кр.1,75-12.



5012 (3.8)
Кр.2,0-36.



5013 (2.68)
Кр.1,5-36.



5014 (2.1)



5015 (4.96)
Кр.1,5-36.



5016 (1.02)
Кр.1,75-5.



5017 (1.3)
Кр.2,0-1; кр.1,5-12.



5018 (0.8)
Кр.2,0-1.



5019 (1.12)
Кр.1,75-6.



5020 (2.87)
Кр.1,5-33.



5021 (4.0)
Кр.2,0-32



5022 (3.7)
Кр.5,0-1; кр.1,25-32



5023 (1.8)



5024 (3.79)
Кр.1,0-88



5025 (4.5)
Кр.1,5-1; кр.1,0-16



5026 (7.6)
Кр.1,25-74



5027 (3.7)



5028 (2.27)
Кр.1,25-32



5029 (1.0)
Кр.2,0-1



5030 (2.08)
Кр.3,0-1; кр.1,25-23

Кресты



5031 (2.1)
Кр.1,25-16



5032 (3.8)



5033 (2.5)
Кр.1,0-100



5034 (5.7)



5035 (3.5)
Кр.1,5-78



5036 (1.96)



5037 (1.57)
М-9 5x2-5; кр.1,5-6



5038 (2.47)
Кр.1,25-24



5039 (1.74)



5040 (1.1)



5041 (3.12)
Кр.1,5-80



5042(4.49)
Кр.4,0-1; кр.3,5-1; кр.3,0-4; кр.2,5-4; кр.2,0-4; кр.1,5-1



5043 (1.19)
Кр.1,5-4



5044 (2.53)
Кр.1,5-40



5045 (1.63)



5046 (7.07)



5047 (4.05)



5048 (3.06)



5049 (1.63)



5050 (1.6)



5051(6.7)



5052 (8.6)



5053 (1.8)



5054 (7.2)



5055 (4.0)



5056 (5.0)



5057 (2.4)



5058 (2.9)
Кр.2,0-1



5059 (2.4)
Кр.1,25-24



5060 (2.2)

Кресты



5061 (4.4)



5062 (2.27)



5063(2.6)



5064 (6.67)



5065 (2.93)



5066 (2.27)

Кр.2,0-13; кр.1,5-28; кр.1,25-4



5067 (3.15)



5068 (3.59)



5069 (3.43)

Кр.1,5-48



5070 (4.58)



5071 (1.83)



5072 (2.71)

Кр.1,5-4



5073 (3.96)



5074 (1.83)



5075 (2.16)

кр 3-1



5076 (2.27)

Кр 1-30



5077 (1.2)

Кр 1-9



5078 (0.8)

Кр 1.5-17



5079 (1,75)

кр 1,25-62



5080 (1,57)

кр 1,25-12

Кресты